

**AMP SUPERSEAL 1.5® a 3 poli**  
**AMP SUPERSEAL 1.5® 3-poles**  
**AMP SUPERSEAL 1.5® de 3 polos**



- Connettore tipo AMP Superseal® 1.5 3 POS.
- Indicatore di apertura/chiusura
- LED di presenza alimentazione e stato comando
- Membrana di sfiato traspirante in PTFE

- AMP Superseal® 1.5 3 POS. connector
- Opening/closing indicator
- Power supply and command status LED
- Breather membrane in PTFE

- Conector tipo AMP Superseal® 1.5 3 POS.
- Indicador de apertura/cierre
- LED con indicación presencia alimentación y estado de comando
- Membrana de ventilación traspirante en PTFE

**Funzionamento a 3 fili**

- Alimentazione 12 Vdc sempre collegata
- Fornendo la tensione di comando (12 Vdc su PIN 3), la valvola ruota in senso orario.
- Togliendo la tensione comando (PIN 3), la valvola ruota in senso antiorario.

**3-wire operation**

- 12 Vdc power supply always on
- With opening/closing command supplied with 12 Vdc on PIN 3, the valve turns clockwise.
- Disconnecting the command power supply (PIN 3), the valve turns counter-clockwise.

**Funcionamiento de 3 cables**

- Alimentación 12 Vcc siempre conectada
- Alimentando el mando de apertura/cierre de 12 Vcc en PIN 3 la válvula gira en el sentido horario.
- Quitando tensión al mando (PIN 3), la válvula gira en el sentido antihorario.

**Funzionamento a 2 fili**

- Movimento di rotazione ottenuto invertendo la polarità di alimentazione con un doppio deviatore.

**2-wire operation**

- Rotation obtained by inverting the power supply polarity with a double switch.

**Funcionamiento de 2 cables**

- Movimiento de rotación obtenido invirtiendo la polaridad de alimentación con un doble conmutador.

In entrambi i casi il motore assorbe corrente solo durante il movimento della valvola.  
 In both cases, the motor absorbs current only during the valve movement.  
 En ambos casos, el motor absorbe corriente solo durante el movimiento de la válvula.

